



Note:
 1. Put bridges between the vsl and the wharf by mobile crane.
 2. Offload the crane by winches on the vsl.

2	0.7m fender	welded	1	2	
1	3.66m bridge beam	welded	1	4	
NO.	SUB-NO. or STDD	NAME & SIZE	MTRL or STYLE	QTY/SET	SET
	J277A-F402	offloading the crane			
ZPMC		TECH.		TRACE	
DRAW	CHK	STDD		CHK	

